Section: ENGINE

Ref: 01.00.4



Fig.	P/n	QTY	Name
Notes:			
[FRUTTET(O II 75]		
[FROTEDIX	5 K 70]		
3	2.3199.312.2/10	1	plug
5	2.0439.273.7	8	stud bolt m 8
6	2.1559.188.2	4	bush 11.4 x 14 x16
7	2.1539.193.0	8	special oil seal 107.62x2.62
8	2.1560.010.0	1	gasket 14.2 x 20
9	2.3199.292.0	1	plug 1/4" gas
10	0.013.0489.4/30	1	crankcase
10.1	2.3130.001.1	10	plug 1/8" gas
10.2	2.3130.002.1	2	plug 1/4" gas
10.3	2.3130.003.1	6	plug 3/8" gas
10.4	0.000.0000.1		cannot be supplied
10.4.1	0.065.1112.7	1	support
10.4.1.2	2.1699.165.0	1	bush 12.3x15x16
10.4.2	0.065.1114.0/10	3	support
10.4.3	0.065.1116.3	1	support
10.4.3.2	2.1699.165.0	1	bush 12.3x15x16
10.4.5	0.065.1140.0	4	special bushing 59X55X20
10.4.6	0.065.1141.0	1	special bushing 59X55X30
10.4.7	0.066.1151.0	1	pin
10.4.8	0.065.1117.0	10	screw m 12 x 100
10.5	2.3179.012.0	1	plug 60
11	0.066.1152.0/10	4	gasket
13	2.1549.154.2	4	bush 4.8x5.8x16
25	0.013.4946.0/10	1	sprayer nozzle
26	2.3120.101.0	1	plug m 18 p.1.5
28	2.1560.014.0	1	washer 18.2 x 24

9_M8211_00_0_A

10.2 -10.4.6 -10.4.5
10.4.7
10.4.1.2 11 10.4.8 10.4.2 10.4.2 10.4.3
10.4
10




Section: ENGINE

Ref: 01.00.10

TIMING CASE

Fig.	P/n	QTY	Name	
Notes: [FRUTTE	то п 75]			
4	2.0432.009.7	1	stud bolt m 8 p.1.25 / p. 1 x 35	
15	2.0432.003.7	1	stud bolt m 8 p.1.25 / p.1 x 20	
16	2.0312.214.2	7	screw m 8 p.1.25 x 40	
17	2.1480.014.1	15	washer 8	
18	0.013.4981.0	1	guard	
19	0.065.1150.0/30	1	gasket	
20	2.1470.004.2	4	lock washer 8	
21	2.1011.405.2	2	nut m 8 p.1	
22	2.0312.208.2	8	screw m 8 p.1.25 x 25	
23	2.1529.167.0	1	oil seal	




9_M8211_00_0_B

Section: ENGINE


Ref: 01.00.13



Fig.	P/n	QTY	Name
Notes: [FRUTTETO II	75]		
1	0.007.1262.3/50	1	guard
2	0.007.1271.0/10	1	small column m 8 p.1.25 / L = mm 60
3	0.007.1272.0/10	2	small column m 8 p.1.25 / $L = mm 50$
5	2.1310.004.2	3	flat washer 8.4x17
7	2.0112.203.2	3	screw m 8 p.1.25 x 12



9_33011_02_0_0



9_34811_03_0_0

FRUTTETO II 75 -> 15001

Section: ENGINE Ref: 01.00.16


MONOBLOC ENGINE-GEARBOX CONNECTING FLANGE


Fig.	P/n	QTY	Name
Notes: [FRUTTE	то п 75]		
6	2.0439.250.7	1	stud bolt m 12 / m 10 x 30
7	0.011.9294.0/10	1	bush
40	0.007.1414.0/10	1	flange
41	2.0112.511.2	8	screw m 14 p.2 x 30
42	2.1651.912.0	2	cylindrical plug 12x28
43	2.0432.257.7	1	stud bolt m 12 p.1.75 - 1.25 x 30
44	2.0312.516.2	2	screw m 14 x 50
45	2.1480.018.1	2	washer 14
46	2.3131.003.2	1	plug m 16 p.1.5

Section: ENGINE

Ref: 01.00.22









Section: ENGINE Ref: 01.00.34

CYLINDER - PISTON - CONNECTING ROD

Fig.	P/n	QTY	Name
Notes: [FRUTTE]	го п 75]		
1	0.082.0065.A	4	cyl. piston assembly "A" - CLASS A
1	0.082.0065.B	4	cyl. piston assembly "B" - CLASS B
1.2	0.A12.2675.0	1	engine cylinder "A" - CLASS A
1.2	0.B12.2675.0	1	engine cylinder "B" - CLASS B
1.3	0.082.0060.A	1	complete piston "A" - CLASS A
1.3	0.082.0060.B	1	complete piston "B" - CLASS B
1.3.1	0.086.0052.6/10	1	piston ring set
1.3.2	2.1411.014.1	2	circlip 35
1.3.3	0.078.1236.0	1	piston pin Ø $18 / Ø 35 / L = mm 86$
2	0.078.1220.3/30	4	engine connecting rod
2.1	2.1559.114.0/10	1	special bushing
2.2	2.0399.213.0	2	screw m 12 p.1.25x61.5
3	0.065.1225.0	8	con.rod half bushing STANDARD - $A = 28.75 \rightarrow 29.00$
3	0.065.1225.7	8	con.rod half bushing - mm 0.25
3	0.065.1225.8	8	con.rod half bushing - mm 0.50





9_33212_08_0_0


FRUTTETO II 75 -> 15001

Section: ENGINE

Ref: 01.00.43

ENGINE FLYWHEEL

Fig.	P/n	QTY	Name	
Notes: [FRUTTE	то п 75]			
1	0.330.1250.0	6	screw m 12 p.1.25x98	
2	0.332.1247.3/10	1	flywheel	
2.2	0.065.1242.0	1	crown wheel $Z = 123$	
3	2.2041.008.0	1	ball bearing 20x47x14	




9_34512_06_0_0

FRUTTETO II 75 -> 15001

Section: ENGINE Ref: 01.00.46

CRANKSHAFT PULLEY - FOR TRACTORS WITH AIR CONDITIONING

Fig.	P/n	QTY	Name
Notes: [FRUTTE	го п 75]		
3	0.007.1458.0/40	1	pulley
5	0.085.1248.0/20	1	hub
6	2.0399.144.7	1	screw m 20 p.1.5x51
8	2.1720.006.0	1	key 4x6.5



9_33312_02_0_0

FRUTTETO II 75 -> 15001

Section: ENGINE Ref: 01.00.49

CRANKSHAFT PULLEY - FOR TRACTORS WITHOUT AIR CONDITIONING


Fig.	P/n	QTY	Name
Notes: [FRUTTE	ТО П 75]		
3	0.007.1457.0/30	1	pulley
5	0.085.1248.0/20	1	hub
6	2.0399.144.7/10	1	screw m 20 p.1.5x51
8	2.1720.006.0	1	key 4x6.5

Section: ENGINE


Ref: 01.00.52

PULSE WHEEL

Fig.	P/n	QTY	Name
Notes: [FRUTTE	ГО П 75]		
1	0.011.3531.0	1	gear Z = 48



9_36812_05_0_0



9_34512_07_0_0

FRUTTETO II 75 -> 15001

Section: ENGINE Ref: 01.00.55

PROVISION FOR FRONT PTO MOUNTING

Fig.	P/n	QTY	Name
Notes: [FRUTTE	то п 75]		
1	0.082.1244.0/10	1	pulley
2	0.011.3515.0/20	1	hub $Z = 48$
3	0.065.1256.0	2	ring 45x52
4	2.1579.865.0	1	spacer 45.2x51.8x10
5	2.0439.195.7	1	stud bolt m 20 p.1.5x80
6	2.1019.094.7	1	nut m 20 p.1.5

Thank you so much for reading.

Please click the "Buy Now!"

button below to download the complete manual.



After you pay.

You can download the most perfect and complete manual in the world immediately.

Our support email: ebooklibonline@outlook.com